

## **NOTES**

1) LEGAL DESCRIPTION: LOT 13, BLOCK G, THE ASPEN HIGHLANDS VILLAGE P.U.D., ACCORDING TO THE PLAT THEREOF RECORDED OCTOBER 15, 1998 IN PLAT BOOK 47 AT PAGE 1, PITKIN COUNTY, COLORADO.

BEARINGS BASED ON THE NORTH LINE OF LOT 13, BLOCK G, THE ASPEN HIGHLANDS VILLAGE P.U.D., RECORDED IN PLAT BOOK 47 AT PAGE 1. BEING A BEARING OF S79°42'26"E BETWEEN A FOUND #5 REBAR AND 1¼" YPC ILLEGIBLE AT THE N.W. PROPERTY CORNER AND A FOUND #5 REBAR AND 1¼" RPC LS# 20133 AT THE N.E. PROPERTY CORNER.

3) THIS SURVEY DOES NOT CONSTITUTE A TITLE SEARCH BY THIS SURVEYOR. TITLE INFORMATION RELIED UPON FOR THE PREPARATION OF THIS SURVEY FURNISHED BY ATTORNEYS TITLE INSURANCE COMPANY, LLC, COMMITMENT NO. 23005182, DATED 09/29/2023. IF AN EXCEPTION IS NOT SHOWN HEREON, IT EITHER DOES NOT AFFECT THE PARCEL, NOT A SURVEY MATTER OR IS NOT PLOTTABLE.

4) UNIT OF MEASUREMENT FOR THIS SURVEY IS THE U.S. SURVEY FOOT.

## LEGEND

● INDICATES FOUND MONUMENT AS DESCRIBED.

RPC 11/4" RED PLASTIC CAP ON #5 REBAR

YPC 11/4" YELLOW PLASTIC CAP ON #5 REBAR

(R) RECORD (A) ABOVE GRADE

(F) FIELD (G) AT GRADE

EM ELECTRIC METER ⊗ CURB STOP

S SEWER MANHOLE WY WATER VALVE

GAS LINE MARKER

TELEPHONE RISER

CLEAN OUT


ELECTRIC TRANSFORMER


FIRE HYDRANT

## SURVEYOR'S CERTIFICATE

I, MICHAEL P. LAFFERTY, HEREBY CERTIFY TO MICHAEL BEYER, CARYN BEYER, ATTORNEYS TITLE INSURANCE AGENCY OF ASPEN, LLC AND FIRST AMERICAN TITLE INSURANCE COMPANY THAT THIS MAP ACCURATELY DEPICTS AN IMPROVEMENT SURVEY PLAT PERFORMED UNDER MY SUPERVISION ON 09/2023 OF THE ABOVE DESCRIBED PARCEL OF LAND. THE LOCATION AND DIMENSIONS OF ALL IMPROVEMENTS, EASEMENTS, RIGHTS-OF-WAY IN EVIDENCE OR KNOWN TO ME AND ENCROACHMENTS BY OR ON THESE PREMISES ARE ACCURATELY SHOWN.

MICHAEL P. LAFFERTY PLS. # 37972





DATE SURVEYED: 09/2023 DATE REVISED: FILE NO: 230886 CLIENT: CHOPIVSKY

NOTICE: According to Colorado law you must commence any legal action based upon any defect in this survey within three years after you first discover such defect. In no event may any action based upon any defect in this survey be commenced mor than ten years from the date of the certification shown hereon.